SPATE (1) / environmental services

July 25, 1989

Yoco, Inc.
P. O. Box 78
White Plains, North Carolina 27031

Re: Laboratory Analysis Results for Tank Closure Soil Samples Neighbors No. 3 Hwy. 601 Mt. Airy, NC

Dear Mr. Atkins:

Enclosed are the laboratory analyses for two (2) soil samples obtained on July 10, 1989 at the location referenced above. The samples were collected from the excavation that resulted from the removal of one (1) 4,000 gallon Kerosene tank. The excavated tank appeared to be in good condition; however, a slight kerosene odor was present in the excavation.

Two (2) hand auger borings were advanced into the native soil below the floor of the tank excavation. These borings were located at opposite ends of the tank excavation (see enclosed site sketch). The hand auger used to collect the soil samples was thoroughly decontaminated prior to and between collection of each individual soil sample. Each sample was split into duplicates, one half evaluated with an organic vapor analyzer (OVA) for possible hydrocarbon contamination and the other half placed in a new, clean glass jar for laboratory analysis. soil samples collected for laboratory analysis were immediately placed in a chilled cooler, refrigerated while stored at SPATCO Environmental offices, and shipped in a chilled cooler to the subcontract laboratory. A copy of the chain of custody record is enclosed to verify that the samples arrived at the laboratory intact, and at proper temperature. The soil samples were analyzed for Total Petroleum Hydrocarbons (TPH) - Mid-Boiling Range and Benzene, Toluene, Ethylbenzene and Total Xylene (BTEX).

Sample #	Depth Collected	OVA Reading	TPH Mid- Boiling	Benzene	Toluene	Ethyl- Benzene	Total Xylene
HB-1-8.5	8.5 ft.	0 ppm	ND*	ND*	ND*	ND*	ND*
HB-2-9.0	9.0 ft.	2 ppm	ND*	ND*	ND*	ND*	ND*

^{*} ND - No detection at a specific detection level.

Yoco, Inc. July 25, 1989 Page Two

The laboratory results indicate that, if hydrocarbon contamination is present, it is present in concentrations below the level the laboratory can detect.

As no significant hydrocarbon contamination in the soil samples was detected, no further investigation or action is required (Federal Regulation 40 CFR 280.52(b)). However, it would be in your best interest to report these findings to the N. C. Division of Environmental Management.

If you have any questions, please contact me.

Sincerely, SPATCO Environmental

alex Mc Jilwan

Alex McGilvary 'Staff Geologist

AMc; jh

cc: Ms. Jessie Davis



SURRY COUNTY,

APPLICATION/PERMIT FOR CONSTRUCTION OR OTHER WORK

TELEPHONE: 919/374-5071 OR 919/366-2886

DATE: 07/10/89

PERMIT NO. 4486

TOUNSHIP

FRINGE. TN LMTS

ZONE 2

OTHER

WATER séwas

MT. AIRY

ZONING

TYPE: TI

LAND AREA:

CERT. #:

PROPERTY QUINER NEIGHBORS INC.

DESCRIPTION HWY 601 AT NEIGHBORS STORE

PO BOX: 48

MT. AIRY, NO 27030

TOTAL CONSTRUCTION COST:

CONTRACTOR INFORMATION

TYPE LIC. # MECH OWNER

CONTRACTOR NEIGHBORS INC. ADDRESS

PO BOX 48

MT. AIRY, NO

BILLING INFORMATION

8.60 E: 0.00 H:

0.99 A: 9.99 I:

ପ.୨୨ ଟ:

TOTAL FEE:

25.00

BILL TO: NEIGHBORS INC.

pd 07-10-89

The undersigned does hereby declare that the information given above is correct and agrees to comply with all state and local laws. local ordinances and regulations, the N.C. State Building Code, and any restrictions as shown below. The applicant furthermore declares that he/she is the property owner or he/she does truly represent the property owner.

APPLICANT'S SIGNATURE

APPROVAL BY

DATE:

DATE: 7-10.89

Checked W/

Lab-


modified method

used is OK

for Kerosene

EFG

9/21/89



SAMPLING POINT

YOCO INC.STORE #063 NEIGHBORS #3 HWY 601 MT. AIRY, NC WO #43556

NOT TOSOLE



556 L ARBOR HILL ROAD KERNERSVILLE, NORTH CAROLINA 27284 PHONE 919/996-0573 SOUTHERN PUMP & TANK COMPANY

Chain of Custody Record

															ЯЕМАЯКЗ:
			BULL SEVE CONTINUE	S ñ	7-259 (Ka)	7.25%	657		0. Z	CHEVIED BY		TILE THE AIRBEL NO.	, p	ORATORY BY	TOTAL LABORATORY BY
								ONLY	ISE	<u>F</u>		1 1			
	TIME	DATE	RELINQUISHED BY:	TIME	DATE			RECEIVED BY:	TIME REC	DATE TI		RELINQUISHED BY:	TIME RE	DATE	RECEIVED BY:
2		7/11/89 13 00	Martin A. Mc Schrony	<u> </u>											REMARKS
						_									
				_	-					: !					
					 -			-							
						_									
					-										
				-	-										
				-	_	_		メ	-	III7 hvs	7-10-89 /1117 hvs	SOIL	۷		HB-2-9.0
				十	-		_	×	-	11 0	7-10-89/11 lows	SOIL	~		HB-1-8.5
	Š	(for lab use only)	REMARKS (for I	<u> </u>	+			Tr		TIME	DATE/TIME	SAMPLE MATRIX	SAMF		FIELD SAMPLE I.D.
	<u>, , </u>	SAM ID NO.	&	_	_		776	ÞH	NO			4			
						_	× nic	(mic	OF C			}	mre gridad	مكادكه	COLLECTED BY (Signature)
					_			d-boili	NIATNO		がいて	HWY GOI, MT AIRY, NC	Hwy (#3,	SITE NETCHBORS
					ANALYSES	·	್ಕಾ 		ERS			290# 3A	arols .	· INC.,	РПОЈЕСТ УОСО
		 <u>a</u> 	Page 1									,			

4 (Pe Received: 07/12/89

REPORT SPATCO

ď

RAS

Work Order # S9-07-075

Sacramento REPORT 07/19/89 05:34:22

Alex McGilvaru Environmental Division 536-L Arbor Hill Rd. Kernersville, NC 27284 PREPARED Radian Analytical Services PHOME ATTEN BY 10395 Old Placerville Road Sacramento, California 95827

FACILITY

Environmental Division

(919) 996-0573

COMPANY

SPATCO ENVIR

SAMPLES

CLIENT

ATTEN

WORK ID

TRANS TAKEN

07/10/89

Yoco Inc., Store #063

TYPE

916-362-5332

CERTIFIED BY

CONTACT LMDAY

SAMPLE IDENTIFICATION

INVOICE P.O. #

under separate cover

<u>Soil</u> 5419102/W.O. #43556 Fedex: 2208507206

HB-1-8. 5 SOIL REAGENT BLANK SOIL HB-2-9. 0 SOIL

TEST CODES and NAMES used on this report

TPH S Extraction for TPH by SP TPH by GC - mod. sw8015

Page 2 Received: 07/12/89

RAS Sacramento REPORT
Results By Test

Work Order # 59-07-075

EX_TPH	TEST CODE
07/12/89	(entered units)
07/12/89 DATE COMPLETED	Sample 02 (entered units)
07/12/89 DATE COMPLETED	Sample 03 (entered units)

Page 3 Received: 07/12/89

RAS Sacramento REPORT
Results By Test

Work Order # 59-07-075

SAMPLE I	Test: EX TPH Date Completed
0	07/12/89
HB-1-8. 5 SOIL	DATE COMPLETED
HB-2-9.0 SOIL	DATE COMPLETED
요 :	07/12/89
REAGENT BLANK S DATE COMPLETED	DATE COMPLETED

Page 4 Received: 07/12/89

RAS Sacramento REPORT

Results by Sample

Work Order # 59-07-075

EX_TPH_07/12/89	SAMPLE ID HB-1-8.5 SOIL
	SAMPLE # 01 FRACTIONS: A Date & Time Collected 07/10/89
	Category

S alte Received: 07/12/89

> Sacramento REPORT

RAS

Work Order # 89-07-075

Results by Sample

SAMPLE ID HB-1-8. 5 SOIL FRACTION OIA TEST CODE TPH S
Date & Time Collected 07/10/89 Category

NAME IPH by GC - mod. su8015

								AMALYST _ INSTRMT _	SOIL TOTAL
								A MC	PETROLEUN
106-93-4			1330-20-7	100-41-4	108-88-3	71-43-2	CAS#	INJECTI	SOIL TOTAL PETROLEUM HYDROCARBONS -
1,2-Dibromoethane	TPH Mid-Boiling(3)	TPH Gasoline(2)	Total Xylenes(2)	Ethylbenzene(2)	Toluene(2)	Benzene(2)	COMPOUND	FILE #	- CALIFORNIA LUFT (1)
NA	ND	NA	ND	NO NO	UN	ND	RESULT	A1907144	
5, 0	5000	50	0, 50	0. 30	0, 30	0. 30	DET LIMIT		VERIFIED
 	100		 	l l l l l			FACTOR	UNITSUg/Kg	ED UD

See Appendix A for Glossary of Report and Data Flag Definitions EPA 5030 (purge & trap) followed by GC analysis with PID/FID d. Extraction using EPA 3520 (sonication) followed by GC analysis detectors.

with FID detector.

Page 6 Received: 07/12/89

SAMPLE ID HB-2-9, O SOIL

RAS Sacramento REPOK Results by Sample REPORT

Work Order # 59-07-075

SAMPLE # 02 FRACTIONS: A
Date & Time Collected 07/10/89 Category

EX_TPH_07/12/89

Received: 07/12/89

RAS Sacramento

Results by Sample

Work Order # 89-07-075

SAMPLE ID HIS-2-9, O SOIL

FRACTION <u>O2A</u> TEST CODE TPH S Date & Time Collected <u>07/10/89</u>

NAME IPH by GC - mod. se8015 Category

								ANALYST _	SOIL TOTAL
								A MC	PETROLEUM
106-93-4			1330-20-7	100-41-4	108-88-3	71-43-2	CAS#	INJECTEL	SOIL TOTAL PETROLEUM HYDROCARBONS -
1,2-Dibromoethane	TPH Mid-Boiling(3)	TPH Gasoline(2)	Total Xylenes(2)	Ethylbenzene(2)	Toluene(2)	Benzene(2)	COMPOUND	INJECTED <u>07/14/89</u> FILE # _	- CALIFORNIA LUFT (1)
NA	NS I	110	ND	CN	NB	ND	RESULT	A1907145	
5, 0	5000	ŭ O	0.50	0.30	0.30	0.30	DET LIMIT		VERIFIED
p-rat.	100	•	put		 		FACTOR	ONITS	ED UD
								uq/Kq	

See Appendix A for Glossary of Report and Data Flag Definitions
 EPA 5030 (purge & trap) followed by GC analysis with PID/FID detectors.
 Extraction using EPA 3520 (sonication) followed by GC analysis

Extraction using EPA 3520 (sonication) followed by 9C analysis with FID detector.

B alte Received: 07/12/89

RAS Sacramento REPORT
Results by Sample

Work Order # 59-07-075

SAMPLE ID REAGENT BLANK SOIL EX_IPH_07/12/89 SAMPLE # 03 FRACTIONS: A
Date & Time Collected not specified Category

Page 9 Received: 07/12/89

RAS Sacramento

REPORT

Work Order # 59-07-075

Results by Sample

SAMPLE ID REAGENT BLANK SOIL FRACTION <u>O3A</u> TEST CODE TPH S NA Date & Time Collected not specified NAME TPH by GC - mod. su8015 Category

Ø

	TPH Ga	1330-20-7 Total)	100-41-4 Ethyll	108-88-3	71-43-2	CAS#	INSTRMT MC INJECTED 07/14/89	OIL TOTAL PETROLEUM HYDROCARBONS - CALIFORNIA LUFT (1)
1,2-Dibromoethane	TPH Gasoline(2) TPH Mid-Boiling(3)	Total Xylenes(2)	Ethylbenzene(2)	Toluene(2)	Benzene(2)	COMPOUND	FILE #	1 LUFT (1)
5	NA	ND	NO	QF.	dN	RESULT	A1907141	
О	5000	0, 50	0.30	0.30	0, 30	DET LIMIT		VERIFIED
ent.	100					FACTOR	C	IED JD
							ONITSUg/Kg	

⁽¹⁾ See Appendix A for Glossary of Report and Data Flag Definitions

⁽i) EPA 5030 (purge & trap) followed by GC analysis with PID/FID detectors.

Extraction using EPA 3520 (sonication) followed by GC analysis with FID detector.

Appendix A

Comments, Notes and Definitions



Page: A-2

Radian Work Order: 59-07-075

*	C	ហ	20	ව	סר	アノア	Š	Z,	ND	N _C	Z A	د	ଦ	ш	D	c	B	₽	*
Not confirmed by analysis on 2nd column	nd column not requested	⊅	Detected in blank, result corrected	Outside control limits	Previously confirmed	\ Not available	Not spiked	Analyte not requested	Not detected at specified detection limit	Not calculated	Not analyzad		Exceeds calibration range	Estimated result - see report narrative	Sample diluted for this analyte	Confirmed on second column	ted in blank, result not correc	Analytical and/or post-digestion spike	Est. result less than 5 times detaction limit

Page: A-3

Radian Work Order: S9-07-075

detection limit is approached. uncertainty of the analysis will increase exponentially as the method the method specified detection limit. Studies have shown that the The asterisk(*) is used to flag results which are less than five times These results should be considered

- ♪ extraction or digestion step. digestion spike. These spikes have not been subjected to the This flag indicates that a spike is an analytical and/or post-
- Ø but the sample results are not corrected for the amount in the blank. This flag indicates that the analyte was detected in the reagent blank
- O Most methods of analysis by gas chromatography recommend reanalysis on second column. flag indicates that the analyte has been confirmed by analysis on a from interferences that may occur and for analyte confirmation. The C a second column of dissimilar phase to resolve compounds of interest
- fall within the calibration range. second with the sample diluted so that high concentration analyte(s) formed, one at the concentration of the majority of the analytes, and a calibration range of the instrument. Therefore two analyses are perary dilution factor. This flag identifies all analytes identified in analysis at a second-In an analysis some compounds can exceed the

U

ì

Page: A-4

Radian Work Order: 59-07-075 E

report narrative. ference. The reported value is estimated because of the presence of inter-The potential source of the interference is included in the

- Q) extract is diluted and re-analyzed. compounds have a response greater than full scale, the sample or calibration range for that specific analysis. Usually if one or more This flag identifies a GC/MS result whose concentration exceeds the
- <u>_</u> criteria but the result is less than the sample quantitation limit. data indicate the presence of a compound that meets the identification where a response factor of I is assumed, or when the mass spectral when estimating a concentration for tentatively identified compounds Indicates an estimated value for GC/MS data. This flag is used either

NA This analyte was not analyzed.

S considered insignificant. spike added concentration because the spike added concentration is not calculated when the sample result is greater than four times the unreliability of data near the detection limit. A spike recovery is Applies to RPD and spike recovery results. The relative percent differ ferences are present. See * definition for further explanation of the is less than five times the detection limit or obvious matrix interence (RPD) and spike recovery are not calculated when a result value

Page: A-5

Radian Work Order: S9-07-075 ND

at or above the the < symbol is the method specified detection limit for the sample. This flag (or <) is used to denote analytes which are not detected specified detection limit. The value to the right of

NR This analyte was not requested by the client.

z this analysis. This analyte or surrogate was not added (spiked) to the sample for

A result or value is not available for this parameter, usually a detection limit.

†lag well monitoring program. sampling program of a specific sample source; for example, a quarterly flag is applicable to analyses of samples arising from a regular Most methods of analysis by gas chromatography recommend reanalysis on from interferences that may occur and for analyte confirmation. a second column of dissimilar phase to resolve compounds of interest indicates that the analyte has been confirmed previously. This

TO

Page: A-6

Radian Work Order: 59-07-075 G

difference) values for duplicate analyses and matrix spike/matrix spike duplicate result. tical QC spike, and surrogate recoveries; and to RPD(relative percent ified control limits. This flag is applied to matrix spike, analy-This quality control standard is outside method or laboratory spec-

- 70 and the sample results are corrected This flag indicates that the analyte for the amount in the blank. 5 **E**A detected in the reagent blank
- (r) been obtained using the Method of Standard Addition. flag indicates that a specific result from a metals analysis has
- C flag indicates that second column was not requested. from interferences that may occur and for analyte confirmation. a second column of dissimilar phase to resolve compounds of interest Most methods of analysis by gas chromatography recommend reanalysis on
- analyte was not confirmed and is likely a false positive flag indicates a second column confirmation was performed but the from interferences that may occur and for analyte confirmation. a second column of dissimilar phase to resolve compounds of interest Most methods of analysis by gas chromatography recommend reanalysis on

><

age: A-7

Radian Work Order: 59-07-075

TERMS USED IN THIS REPORT:

EPA method and GC specifications Analyte - A chemical for which a sample is t o œ analyzed. The analysis will meet

Compound - See Analyte.

vary from that specified by EPA based on sample size, dilution or cleanup. on experimental values at the 99% confidence level. Note, the detection limit may specified by EPA. Detection limits which are higher than method limits are based laboratories' method detection limits to verify that they meet or are lower than those quantitation specified by EPA for a method. Radian staff regularly assess their (Refer to Factor, below) The method specified detection limit, which is the lower 0

analyses and standard methods for analysis of environmental samples. EPA Method - The EPA specified method used to perform an analysis. accompanying QC tests in conformance with EPA methods unless otherwise specified. Radian will perform its EPA has specified

matrices (soil or water), use of cleanup procedures, or dilution of extracts/ A factor is required to calculate sample specific detection limits based on alternate Factor - Default method detection limits to 1 liter of water will result in a factor of 100. For example, extraction or digestion of 10 grams of soil in contrast are based on analysis of clean water samples

Matrix ı The sample material. Generally, it will be soil, water, air, oil, or solid

Radian Work Order the analytical summary. The unique Radian identification code assigned с† О the samples reported in

7 Percent; usually used for percent recovery of QC stands/cm conductance unit; microSiemans/centimeter matter implifications and the milliliters per hour; rate of settlement of matter implifications.
